

Declassification Review by NGA/DoD

OUT 56352

P 032017Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5124.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI)

1. CAMERA B 23 WAS USED IN MISSION 8034 FLOWN ON 31 JULY 1965.

PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: INTERMITTENT STATIC TRACES AND EDGE FOG OCCUR
 ALONG BOTH EDGES THROUGHOUT THE MISSION. A ROW OF MINUS DENSITY DOTS
 LOCATED APPROXIMATELY 2.0" FROM AND PARALLEL TO THE INBOARD EDGE
 IS PRESENT FROM HEAD TO TAIL. THE SPACING BETWEEN SUCCESSIVE
 DOTS IS 1.68". INBOARD AND OUTBOARD ROLLER CHATTER IS PRESENT
 THROUGHOUT THE MISSION. SPOTS OF PLUS DENSITY WITH DARKER CENTERS
 BELIEVED TO BE ASSOCIATED WITH THE ROLLER CHATTER ARE INTERMITTENTLY
 PRESENT FROM HEAD TO TAIL. THESE ARE MOST NUMEROUS WITHIN THE FIRST
 200 FRAMES AND GRADUALLY DIMINISH IN FREQUENCY THEREAFTER. THEY
 ARE PRESENT NEAR BOTH THE INBOARD AND OUTBOARD EDGES. A PLUS DENSITY
 LINE LOCATED 7.3" FROM THE INBOARD EDGE BEGINS IN FRAME 1090 AND IS
 CONTINUOUS THROUGH THE END OF THE MISSION. A REPETITIVE PATTERN
 OF PLUS DENSITY STREAKS WHICH OCCURS ABOVE EVERY 45" BEGINS IN

4 AUG 1965

COPIES RECEIVED		
Cy No.	Off	Ac
1	Fig	
2	OS	
	ADMIN	
	SEC BP	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
34	TID	
	PIN	
	DAI	
	DIAXX 4	
	SPAD	
	NSA-LU	
	DIA-AP	

FRAME 2093 AND IS PRESENT THROUGH THE END OF THE MISSION. THE LONGEST OF THESE STREAKS IS SLIGHTLY CURVED AND ORIENTED ABOUT IN LINE WITH THE MINOR AXIS. ITS LENGTH IS ABOUT 3.0". ABRASION MARKS RUNNING PARALLEL TO THE MAJOR AXIS ARE PRESENT FROM FILM EDGE TO FILM EDGE OCCURRING INTERMITTENTLY FROM FRAME 1654 THROUGHOUT THE END OF THE MISSION. THESE APPEAR TO HAVE BEEN CAUSED BY A STICKING ROLLER. CHEMICAL STAINS AND EMULSION LIFTS ARE PRESENT IN FRAMES 692/693. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 528/529, 750/751, 1054/1055, 1071/1072, 1087/1088, 1114/1115, 1166/1167, 1207/1208, 1229/1230, 1241/1242, 1250/1251, 1276/1277 AND IN FRAME 1046.

C. 9L SIDE: SMALL STATIC DISCHARGES ARE PRESENT ON BOTH EDGES THROUGHOUT THE FILM. THE INBOARD EDGE ALSO CONTAINS CONTINUOUS CAMERA ROLLER INDUCED STATIC DISCHARGES. A FEW PLUS DENSITY STREAKS ARE NOTED INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM IN FRAMES 481-1200. FINE, CONTINUOUS PLUS DENSITY STREAKS PARALLEL TO AND APPROXIMATELY 1.75" FROM THE INBOARD EDGE ARE PRESENT IN FRAMES 1201 TO 2203. HEAT SPLICES ARE POSITIONED BETWEEN FRAMES 545/546, 1180/1181, 1211/1212, 1691/1692, AND 1733/1734. THE LATTER IS ACCOMPANIED BY A HEAVY EMULSION SCRATCH IN FRAME 1734. A MYLAR SPLICE WITH ASSOCIATED SCRATCHES AND WRINKLES IS PRESENT IN FRAME 1180 AND FRAME 1827 CONTAINS A MANUFACTURER'S SPLICE. A FEW SPLICE ASSOCIATED STATIC DISCHARGES ARE NOTED.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0001 TO 2203.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING

1
FAULTS.

3. DUPLICATE POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURED 20 PERCENT OF THE TERRAIN COVERED IN THIS
MISSION.

S E C R E T

/END OF MESSAGE/